EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2301	(29/599,598).CCLS.	US-PGPUB; USPAT	OR	OFF	2008/02/19 09:53
L2	2045	(310/254).OOLS.	US-PGPUB; USPAT	OR	OFF	2008/02/19 09:54
L3	4290	l1 or l2	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/19 09:54
L4	809	l3 and (weld or welding)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/19 09:55
L5	100	l3 and (weld or welding) and (formula or equation)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/19 09:55
L6	1	l3 and (weld or welding) with (formula or equation)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/19 09:56
L7	3	I3 and (weld or welding) same (formula or equation)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/19 09:56
S1	0	weelding seam	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:08
S2	5016	welding seam	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:09
S3	17	welding seam (depth or thickness or dimension)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:09
S4	968	(weld or welding) with (formula or equation)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:35
S5	373	(weld or welding) with (formula or equation) and (laminations or sheets)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:35

S 6	199	(weld or welding) with (formula or equation) and (laminations or sheets) with (weld or welding)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:39
S7	20	(weld or welding) with (formula or equation) and (laminations or sheets) with (weld or welding) and tolerance	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:39
S 8	7	(weld or welding) with (formula or equation) and (laminations) with (weld or welding)	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/12 16:43
S9	1	("5992013").PN.	US-PGPUB; USPAT	OR	OFF	2008/02/13 15:27
S10	20	("4546443" "4608494" "4683644" "5010474" "5075559" "5214841" "5265330" "5383270" "5547537").FN. OR ("5992013").URPN.	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/02/13 15:29

^{2/19/2008 9:56:50} AM

C:\ Documents and Settings\ Icazan\ My Documents\ EAST\ Workspaces\ 10527917 \ 2008.02.12.wsp